


RunChart



$\bar{x}$  = 10.01  
 $s$  = 0.01  
target = 10.003  
 $C_g$  = 1.08  
 $C_{gk}$  = 0.91

